

Photo Album for Carver, MA Job 29258-02 March 25, 2016

This week the cab finished on the cab line and has been merged with the chassis along with the pump.

The body finished in paint and was completing the body line where harnessing and trim were added. Next week the chassis is scheduled to begin on the main assembly line where the body and water tank should be merged with the chassis.

ITEM NO. 29258-02

TRUCK NO. _____

INTERNAL ORDER NO. 19428356

AERIAL NO. 19438731

TORQUE BOX NO. _____

V.I.N. NO. 016562

CHASSIS BY: ☒ PIERCE ☐ CUSTOMER

DEALER: Minuteman Fire & Rescue

CUSTOMER: Town of Carver Fire Dept.

STATE: MA

C/M: Streck

PAINT NO: #80

SPECIAL INSTRUCTIONS:

PT BK ☐ Vinyl ☐ GS ☐ Nothing ☐ No Trim

☐ Vinyl Material ☐ Wheel Striping ☐ Special Color

☐ Scotchlight ☐ Sign Gold ☐ Goldletter ☐ Traditional

☐ Previous Pierce Customer Truck # _____

☐ NO GRAPHICS ☐ DOT ONLY

DSC03179



DSC03180



DSC03181



DSC03182



DSC03183




DSC03184




DSC03185



DSC03186



DSC03187



DSC03188



DSC03189



DSC03190



DSC03191



DSC03192



DSC03193



DSC03194



DSC03195



DSC03196



DSC03197



DSC03198



DSC03199



DSC03200



DSC03201



DSC03202



DSC03203



DSC03204



DSC03205




DSC03206



DSC03207



DSC03208



DSC07729




DSC07730



DSC07731



DSC07732



DSC07733