





Photo Album for Carver, MA Job 29258-03 March 18, 2016

This week the cab continued assembly. The chassis began assembly. The body completed fabrication and began the paint process. Next week the cab and pump should be merged with the chassis. The body should finish in paint and begin on the body line where harnessing and trim are added.



DSC07349



DSC07350



DSC07351



DSC07352



DSC07353



DSC07354



DSC07355



DSC07356



DSC07357



DSC07358



DSC07359



DSC07360




DSC07361



DSC07362



DSC07363



DSC07364



DSC07365



DSC07366



DSC07367



DSC07368



DSC07369



DSC07370



DSC07371



DSC07372



DSC07373



DSC07374



DSC07375



DSC07377



DSC07378



DSC07379



DSC07380



DSC07381



DSC07382



DSC07383



DSC07384



DSC07385



DSC07386



DSC07387



DSC07388



DSC07389



DSC07390



DSC07391



DSC07392



DSC07393




DSC07394



DSC07395



DSC07396



DSC07717



DSC07718



DSC07719



DSC07720



DSC07721



DSC07722



DSC07723



DSC07724



DSC07725



DSC07726



DSC07727




DSC07728



DSC07729




DSC07730



DSC07731



DSC07732



DSC07733



DSC07734



DSC07735



DSC07736



DSC07737




DSC07738



DSC07739



DSC07740



DSC00486



DSC00487



DSC00488



DSC00489



DSC00490