


# Photo Album for Carver, MA Job 29258-03 March 25, 2016

This week the cab finished on the cab line and has been merged with the chassis along with the pump. The body finished in paint and was on the body line where harnessing and trim are added. Next week the chassis is scheduled to begin on the main assembly line where the body and water tank should be merged with the chassis.





DSC07704



DSC07705



DSC07706



DSC07707





DSC07708



DSC07709



DSC07710



DSC07711






DSC07712



DSC07713



DSC07714



DSC07715





DSC07716



DSC07717



DSC07718



DSC07719





DSC07720



DSC07721



DSC07722



DSC07723






DSC07724



DSC07725



DSC07726



DSC07727





DSC07728



DSC00022



DSC00023



DSC00024





DSC00025



DSC00026