




Photo Album for Concord, NH Job 29635 May 13, 2016

This week the cab finished in paint while the pump had some valves installed. The pump house structure and body began in fabrication. Next week the cab should begin on the cab line where cab related content is added. The chassis is scheduled to begin assembly. The pump should be installed in the pump house while the body panels should be joined in fabrication.



DSC04494



DSC04495



DSC04496



DSC04497



DSC04498



DSC04499



DSC04500



DSC07154



DSC07155



DSC07156



DSC07157



DSC07197




DSC07198



DSC07199



DSC07200



DSC07091



DSC07092



DSC07093



DSC07094



DSC07095



DSC07096