





Photo Album for Concord, NH Job 29635 May 20, 2016


This week the cab finished in paint and began on the cab line where cab related content is added. The chassis began assembly. The pump house finished initial plumbing. The body completed fabrication and began the paint process in metal finishing. Next week the cab and chassis should be nearing completion in assembly. The pump house may be painted. The body should finish in paint.




DSC04423



DSC04424




DSC04425



DSC04426



DSC04427



DSC02653



DSC02654



DSC02655



DSC02656



DSC02657



DSC02658



DSC02659



DSC02660



DSC02661



DSC02662



DSC02663



DSC02664




DSC02665



DSC02666



DSC02667



DSC02668



DSC02669



DSC02670



DSC02671



DSC02672



DSC08006



DSC08007



DSC08008



DSC08009



DSC08010



DSC02506



DSC02507



DSC02508



DSC02509



DSC02510



DSC02511