


# Photo Album for Cotuit, MA

Job # 29562

W/O # 19782542

March 18, 2016

This week the cab began the paint process. The chassis frame was in transit and not available for photos. Next week the cab should continue with the paint process and the chassis frame should arrive in Florida. The body could begin weld-up and fabrication.



DSC07140



DSC07141



DSC07142



DSC07143



DSC07144