

Photo Album for Cotuit, MA

Job # 29562

W/O # 19782542

March 25, 2016

This week the cab began continued with the paint process. The chassis frame arrived from Appleton and the body began weld up and fabrication. Next week the cab could begin having cab related content installed on the cab line. The chassis may begin initial assembly and the body should finish with fabrication.



DSC06189



DSC06190



DSC06191



DSC06192



DSC06193



DSC06194



DSC06301



DSC06302



DSC06303



DSC06304



DSC06305



DSC06306



DSC06307



DSC06308




DSC06309




DSC06310



DSC06311



DSC06318



DSC06319



DSC06320



DSC06321



DSC06322



DSC06323



DSC06324