

Photo Album for Cotuit, MA

Job # 29562

W/O # 19782542

April 1, 2016

This week the cab finished the paint process and is in staging along with the chassis frame. The pump house structure was fabricated and the body began the paint process. Next week the cab should begin having cab content installed on the cab line and the chassis should begin initial assembly. The pump house could begin initial assembly and the body should continue with the paint process.



DSC06169



DSC06170



DSC06171



DSC06172



DSC06173



DSC06174



DSC06175



DSC06176



DSC06177



DSC06178



DSC06179



DSC06180



DSC06240



DSC06241



DSC06242



DSC06252



DSC06253



DSC06254



DSC06255



DSC06256



DSC06257