


Photo Album for Cotuit, MA

Job # 29562

W/O # 19782542

April 8, 2016

This week the cab began having cab related content installed on the cab assembly line. The chassis frame remained in staging. The main fire pump had valves and plumbing added, the body continued with the paint process and the water tank arrived. Next week the cab should continue on the cab line, while the chassis should begin chassis assembly. The pump and pump house structure should be joined together and begin the paint process. The body should finish with paint.



DSC06392



DSC06393



DSC06394



DSC06395



DSC06396



DSC06397




DSC06398



DSC06399




DSC06400



DSC06401



DSC06402



DSC06403



DSC06404



DSC06405



DSC06406



DSC06407



DSC06608



DSC06609



DSC06610



DSC06611



DSC06612



DSC06613



DSC06614




DSC06707



DSC06709



DSC06710



DSC06711



DSC06712



DSC06713




DSC06714



DSC06715



DSC06716



DSC06721



DSC06722



DSC06723