

Photo Album for Cotuit, MA

Job # 29562

W/O # 19782542

April 29, 2016

This week the chassis continued on the chassis assembly line. The pump house was painted and began pump final assembly and the body remained in staging. Next week your truck should begin final assembly after having the pump house, body and water tank mounted on the chassis.

 		QUALITY SYSTEM Title: Window Sheet Effective Date: 12/01/14 Page 1 of 1	
PWO #:	19782542	Job #:	29562
Chassis Color:	90RED	Top Color: (Two Tone)	10white
VIN #:	GA016593		
Customer:	Cotuit F.D.		
Contract Manager:	Rob Wilkey		
RFP Date:	5/2/16		
Rework Number:	19782542		
CONFIGURATION ☒ PUMPER ☐ TANKER ☐ RESPONDER ☐ RESCUE ☐ BRUSH			

DSC06449




DSC06450



DSC06451



DSC06452



DSC06453



DSC06454



DSC06455



DSC06456



DSC06457



DSC06458



DSC06459



DSC06460



DSC06461



DSC06462



DSC06463




DSC06464



DSC06465




DSC06466



DSC06467




DSC06468



DSC06469



DSC06470



DSC06471



DSC06472



DSC06473



DSC06474



DSC06475



DSC06476



DSC06477



DSC06478



DSC06479



DSC06480



DSC06481



DSC06482




DSC06483



DSC06485



DSC06486



DSC06487



DSC06488



DSC06489



DSC06490




DSC06491



DSC06492



DSC06493



DSC07035



DSC07036



DSC07037



DSC07038



DSC07040



DSC07041



DSC07042



DSC07043



DSC07044




DSC07045



DSC07046



DSC07047



DSC07048



DSC07049




DSC07050



DSC07051




DSC07052



DSC07053



DSC07054



DSC07146



DSC07147



DSC07148



DSC07149



DSC07150



DSC07151



DSC07152