





Photo Album for Dennis Fire Department, MA Job 29656 July 1, 2016

This week the cab finished on the cab line and has been merged with the chassis along with the pump house. The body finished in paint and completed the line where harnessing and trim were added. In the next report the chassis is scheduled to begin on the main assembly line where the body and water tank should be merged with the chassis.

Due to Pierce plant Holiday shut down, your next scheduled report will be July 15, 2016.



DSC08741



DSC08742



DSC08743



DSC08744



DSC08745



DSC08746



DSC08747



DSC08748



DSC08749



DSC08750



DSC08751



DSC08752



DSC08753



DSC08754




DSC08755



DSC08756



DSC08757



DSC08758



DSC08759



DSC08760



DSC08761



DSC08762




DSC08763



DSC08764



DSC08765



DSC08766




DSC08767



DSC08768



DSC08769



DSC08770



DSC08771



DSC08772



DSC08773



DSC08774



DSC08775



DSC08776



DSC08777




DSC08778



DSC08779



DSC08780



DSC08781



DSC08782



DSC08783



DSC08784



DSC08785



DSC08786



DSC08787



DSC08788




DSC08789



DSC08790



DSC08791



DSC08792



DSC08793



DSC08794



DSC08795




DSC08796



DSC08797



DSC08798




DSC08799



DSC08800



DSC08801



DSC08802



DSC08803



DSC08804



DSC08804a



DSC08804b



DSC08804c



DSC08804d



DSC08805



DSC08806



DSC08807



DSC08808



DSC08809




DSC08810



DSC08811



DSC08812



DSC08813



DSC08818



DSC08819



DSC00159



DSC00160



DSC00161



DSC00162



DSC00163