





Photo Album for Duxbury, MA Job 29578 June 17, 2016

This week the cab finished on the cab line and has been merged with the chassis along with the pump plumbing and chassis cooling structure while the body had harnessing and trim added. Next week the chassis should begin on the main assembly line where the body and water tank should be merged with the chassis.



DSC00309



DSC00310



DSC00311



DSC00312



DSC00313



DSC00314



DSC00315



DSC00316



DSC00317



DSC00318




DSC00319



DSC00320



DSC00321



DSC00322



DSC00323



DSC00324



DSC00325



DSC00326




DSC00327



DSC00328



DSC00329



DSC00330




DSC00331



DSC00332



DSC00333



DSC00334



DSC00335




DSC00336



DSC00337



DSC00338



DSC00339



DSC00340



DSC00341



DSC00342



DSC00343



DSC00344



DSC00345




DSC00346



DSC00347



DSC00348



DSC00349



DSC00350



DSC00351



DSC00352



DSC00363



DSC00364



DSC00365



DSC00366



DSC00367