


Photo Album for Essex VT Job 30386 January 13, 2017

Your new Pierce apparatus is now in production. This week the cab was fabricated and it began the paint process in metal finishing. Next week the cab should continue in paint.



DSC00391



DSC00388



DSC00389



DSC00390