





Photo Album for Essex VT Job 30386 February 3, 2017

This week the cab continued assembly while the chassis began assembly. The pump house was painted and continued assembly. The body continued in fabrication. Next week the cab is scheduled to be merged with the chassis and pump house. The body may begin the paint process.



DSC04193



DSC04194




DSC04195



DSC04196



DSC04197



DSC04298



DSC04299



DSC04300



DSC04301



DSC04302



DSC04303



DSC04304




DSC04305



DSC04306



DSC04307




DSC04308




DSC04309



DSC04310



DSC04311



DSC04312



DSC04313



DSC04314



DSC04315




DSC04316



DSC04317



DSC04318



DSC04319



DSC04320



DSC04321



DSC07120



DSC07121



DSC07122



DSC07123



DSC07124

Pierce. PUMPER S
D/A Finish parts sp
Job# 30386 Fixture 3
DA Finish Hosebed Area _____ Hosebed Area Lined v
Night Spots _____
Fill in appropriate boxes only - Highlight d

	Description	Qty.	Clock #	Strip	M/F	Hang	Un-Hang	Clock #
1.	Access Panels (compartments)							
2.	Air Bag Rack							

DSC07114



DSC07115



DSC07116



DSC07117



DSC07118



DSC07119