
## Photo Album for Essex, VT Job # 30387 W/O # 21019282 March 3, 2017

This week the chassis continued with the cab painting process. The main fire pump began having valves and plumbing added. The lower body and water tank side sheets began the paint process. Next week the chassis should finish with cab painting. The pump and pump house structure could be joined together and the lower body should continue with the paint process.



DSC06317



DSC06319



DSC06318



DSC06320





DSC06321



DSC06323




DSC06322



DSC06324





DSC06325



DSC06327



DSC06326



DSC06328





DSC06329



DSC06331



DSC06330



DSC06332





DSC06333



DSC06468



DSC06334



DSC06469






DSC06470



DSC06472



DSC06471



DSC06473






DSC06474



DSC06476



DSC06475

