

# Photo Album for Essex, VT

Job # 30387

W/O # 21019282

March 10, 2017

This week the chassis finished with cab painting and is staged to begin preparations for fire service use. The pump house was painted and the lower body modules continued with the paint process. Next week the chassis should begin in chassis prep. The pump house should begin pump final assembly and the lower body should finish with the paint process.



QUALITY SYSTEM FORM		QSF10-0836	
Title: Window Sheet		Effective Date: 12/01/14	
		Page 1 of 1	
WO #:	21019282	Job #:	
Chassis Color:	90RED	Top Color: (Two-Tone)	101BLACK
VIN #:	HJ172312		
Customer:	Essex Fire Dept		
Contract Manager:	Rob Wilkey		
RFP Date:			
Rework Number:	21019704	Paint at PIERCE	
<u>CONFIGURATION</u>			
<input type="checkbox"/> PUMPER <input checked="" type="checkbox"/> TANKER			

DSC06066



DSC06067



DSC06068



DSC06069





DSC06070



DSC06071



DSC06072



DSC06073





DSC06074



DSC06269



DSC06270



DSC06271





DSC06272



DSC06273



DSC06274



DSC06275





DSC06276



DSC06277



DSC06278



DSC06279





DSC06280



DSC06281



DSC06282



DSC06283