
Photo Album for Freeport, ME Job 29454 April 29, 2016

This week the cab began on the line where cab related content will be added. The chassis began assembly. The pump had valves installed. The body was fabricated. Next week the cab is scheduled to be merged with the chassis and pump. The body should begin the paint process.



DSC04380



DSC04382



DSC04381



DSC04383





DSC04384



DSC02651



DSC02650



DSC02652





DSC02653



DSC02655



DSC02654



DSC02656






DSC02657



DSC02659



DSC02658



DSC02660





DSC02661




DSC02663


Find us on Facebook



DSC02662



DSC02664



DSC02665



DSC02269



DSC02666



DSC02270






DSC02271



DSC02605



DSC02604



DSC02606





DSC02607



DSC02609



DSC02608



DSC02610







DSC02612

