

Photo Album for Grafton, VT

Job # 29259

W/O # 19438988

April 29, 2016

Your new Pierce apparatus is now in production at the Bradenton, FL facility. The chassis has arrived and is in staging along with the main fire pump. This week the pump house structure and body both began weld-up and fabrication. Next week the chassis should remain in staging. The pump house should finish fabrication and the body should finish with fabrication and could begin the paint process.

QUALITY SYSTEM FORM QSP16-0836
 Title: Window Sheet Effective Date: 12/26/14 Page 1 of 1

PWO #: 19438988 Job #: 29259
 Chassis Color: 90RED Top Color: (Two-Tone) 90RED
 VIN #: HHHF9492
 Customer: Grafton F.D
 Contract Manager: Brian Robinson
 RFP Date: 6/9
 Rework Number: 19440068

CONFIGURATION

☒ PUMPER
☐ TANKER
☐ RESPONDER
☐ RESCUE
☐ BRUSH TRUCK
☐ OTHER: _____

DSC06160



DSC06161



DSC06162



DSC06163



DSC06164



DSC06165



DSC06166



DSC06167



DSC06168



DSC06169



DSC06170



DSC06171



DSC06172



DSC06173



DSC06174



DSC06175



DSC06176



DSC06177



DSC06178



DSC06179



DSC06180



DSC06181



DSC06182




DSC06183



DSC06184



DSC06185



DSC06186



DSC06187



DSC06188



DSC06189



DSC06190



DSC06191



DSC06192



DSC06193



DSC06194




DSC06195



DSC06196



DSC06198



DSC06245




DSC06246



DSC06247



DSC06248



DSC06249



DSC06250



DSC06251



DSC06252



DSC06253



DSC06254