

# Photo Album for Grafton, VT

Job # 29259

W/O # 19438988

May 6, 2016

This week the chassis remained in staging. The pump house structure finished fabrication and the body began the paint process. Next week the chassis should remain in staging. The main fire pump could begin having valves and plumbing added and the body should continue with the paint process.

QUALITY SYSTEM FORM		QSF10-0836	
Title: Window Sheet		Effective Date: 12/01/14	
		Page 1 of 1	
PWO #:	19438988	Job #:	29259
Chassis Color:	90RED	Top Color: (Two Tone)	90RED
VIN #:	HHHF9492		
Customer:	Grafton F.D		
Contract Manager:	Brian Robinson		
RFP Date:	6/9		
Rework Number:	19440068		
<u>CONFIGURATION</u>			
<input checked="" type="checkbox"/>	PUMPER		
<input type="checkbox"/>	TANKER		
<input type="checkbox"/>	RESPONDER		
<input type="checkbox"/>	RESCUE		
<input type="checkbox"/>	BRUSH TRUCK		
<input type="checkbox"/>	OTHER:		
Supplied Chassis?		Yes	No

DSC06454



DSC06455



DSC06456



DSC06457



DSC06458



DSC06614



DSC06615



DSC06616



DSC07248



DSC07249



DSC07250



DSC07251



DSC07252



DSC07253



DSC07254