

Photo Album for Grafton, VT

Job # 29259

W/O # 19438988

May 13, 2016

This week the chassis was set to begin preparations for fire service use. The main fire pump and pump house structure remained in staging (no photos). The body continued with the paint process and the water tank arrived. Next week chassis trim, the main wiring harnesses and body supports should begin installation in chassis prep. The pump house could begin initial assembly and the body should finish with the paint process.

QUALITY SYSTEM FORM QSF10-0836
Effective Date: 12/01/14
Page 1 of 1

Title Window Sheet

PWO #: 19438988 Job #: 29259
Chassis Color: 90RED Top Color: (Two Tone) 90RED
VIN #: HHHF9492
Customer: Grafton F.D
Contract Manager: Brian Robinson
RFP Date: 6/9
Rework Number: 19440068

CONFIGURATION

☒ PUMPER
☐ TANKER
☐ RESPONDER
☐ RESCUE
☐ BRUSH TRUCK
☐ OTHER:

DSC06247



DSC06248




DSC06249



DSC06250



DSC06251




DSC06252



DSC06253



DSC06254



DSC06255



DSC06256



DSC06257



DSC06258



DSC06259



DSC06617



DSC06618




DSC06619



DSC06620



DSC06621



DSC06879



DSC06880



DSC06881



DSC06882



DSC06883



DSC06884



DSC06885