


Photo Album for Grafton, VT

Job # 29259

W/O # 19438988

May 20, 2016

This week the chassis began preparations for fire service use. Chassis trim, the main wiring harnesses and body supports are in the process of being installed. The pump house began initial assembly and the body finished with the paint process. Next week the chassis should continue on the chassis prep line and cab content could begin installation. The pump house should be painted and the body could begin having trim and wiring harnesses added.



DSC06172



DSC06173




DSC06174



DSC06175



DSC06176



DSC06177



DSC06178



DSC06179



DSC06180



DSC06181



DSC06182



DSC06183



DSC06184



DSC06185




DSC06186



DSC06187



DSC06188



DSC06189



DSC06190



DSC06191



DSC06192



DSC06193



DSC06194



DSC06195



DSC06196



DSC06393



DSC06394



DSC06395



DSC06396



DSC06397



DSC06398



DSC06399



DSC06400



DSC06401



DSC06402



DSC06610



DSC06611



DSC06612



DSC06613



DSC06614



DSC06615



DSC06616



DSC06617



DSC06618