

# Photo Album for Grafton, VT

Job # 29259

W/O # 19438988

May 27, 2016

This week the chassis continued on the chassis prep line and cab electrical content began installation. The pump house was painted and began pump final assembly, while the body finished with body assembly and is staged for mounting. Next week the chassis should continue on the chassis prep line and the pump house may be mounted on the chassis. The body should remain in staging.

QUALITY SYSTEM FORM  
DATE TO BE FILLED  
EFFECTIVE DATE 1-1-11  
Page 1 of 1

PWO#: 19438988 Job #: 29259  
Chassis Color: 90RED Top Color: 90RED  
VIN #: HHHF9492  
Customer: Grafton F.D  
Contract Manager: Brian Robinson  
REP Date: 6/9  
Howork Number: 19440068  
CONFIGURATION

☒ PUMPER  
☐ TANKER  
☐ RESPONDER  
☐ RESCUE  
☐ BRUSH TRUCK

DSC06717



DSC06718



DSC06719



DSC06720




DSC06721



DSC06722



DSC06723



DSC06724



DSC06726



DSC06727



DSC06728



DSC06729



DSC06730



DSC06731



DSC06732



DSC06734



DSC06736



DSC06737



DSC06738



DSC06739



DSC06740



DSC06741



DSC06742



DSC06743



DSC06744



DSC06745



DSC06746




DSC06747



DSC06748



DSC06749



DSC06750



DSC06751



DSC06752



DSC06753



DSC06754



DSC06755



DSC06756



DSC07130



DSC07131



DSC07132



DSC07133



DSC07134



DSC07135



DSC07136



DSC07137



DSC07138



DSC07139



DSC07140



DSC07141



DSC07142



DSC07144



DSC07145



DSC07341



DSC07342



DSC07343



DSC07344



DSC07345



DSC07346




DSC07347



DSC07348



DSC07349



DSC07350



DSC07351



DSC07352



DSC07353



DSC07354



DSC07355



DSC07356