

Photo Album for Grafton, VT

Job # 29259

W/O # 19438988

June 17, 2016

Since the last report, your truck advanced to the final assembly line after having the pump house, body and water tank mounted on the chassis. Additional option content and reflective striping are in the process of being installed. Next week it should continue with final assembly and could be released to begin initial and third party pump testing.

QUALITY SYSTEM FORM
Title Window Sheet

OSF10-0836
Effective Date: 12/01/14
Page 1 of 1


PWO #: 19438988 Job #: 29259
Chassis Color: 90RED Top Color: (Two Tone) 90RED
VIN #: HHHF9492
Customer: Grafton F.D
Contract Manager: Brian Robinson
RFP Date: 6/9
Rework Number: 19440068
CONFIGURATION

☒ PUMPER
☐ TANKER
☐ RESPONDER

DSC06814



DSC06815



DSC06816



DSC06817



DSC06818



DSC06819



DSC06820



DSC06821



DSC06822



DSC06823




DSC06824



DSC06825



DSC06826



DSC06827



DSC06828



DSC06829



DSC06830



DSC06831



DSC06832



DSC06833



DSC06834



DSC06835



DSC06836



DSC06837



DSC06838



DSC06839



DSC06840



DSC06841



DSC06842



DSC06843



DSC06844



DSC06845



DSC06846



DSC06847



DSC06848



DSC06849




DSC06850



DSC06851



DSC06852



DSC06853



DSC06854



DSC06855




DSC06856



DSC06858



DSC06860



DSC06861




DSC06862



DSC06864



DSC06865



DSC06866



DSC06867



DSC06868



DSC06869



DSC06870



DSC06871



DSC06872




DSC06873



DSC06874



DSC06875



DSC06876



DSC06877




DSC06878



DSC06879



DSC06880



DSC06881



DSC06882



DSC06883



DSC06884



DSC06885



DSC06886



DSC06887