


Photo Album for Hadley, MA Job 29840 September 16, 2016

This week the cab finished in paint. The body began fabrication. Next week the cab is scheduled to begin on the cab line where cab related content is added while the chassis begins assembly. The body may begin the paint process.



DSC04075



DSC04076



DSC04077



DSC04078



DSC04079



DSC04080



DSC04081



DSC07159



DSC07160



DSC07161



DSC07162



DSC07163



DSC07164