





Photo Album for Hadley, MA Job 29840 October 07, 2016

This week the cab finished on the cab line and has been merged with the chassis along with the pump.

The body finished in paint and completed the line where harnessing and trim were added. Next week the chassis is scheduled to begin on the main assembly line where the body and water tank should be merged with the chassis.



DSC00035



DSC00036



DSC00037



DSC00038



DSC00039



DSC00040



DSC00041



DSC00042



DSC00043



DSC00044



DSC00045



DSC00046



DSC00047



DSC00048



DSC00049



DSC00050



DSC00051



DSC00052



DSC00053



DSC00054



DSC00055



DSC00056



DSC00057



DSC00058



DSC00059



DSC00060




DSC00061



DSC00062



DSC00063



DSC00064



DSC00065



DSC00066



DSC00067



DSC00068




DSC00069



DSC00070



DSC00071



DSC00072



DSC00073



DSC00074



DSC00075



DSC00076



DSC00461



DSC00462



DSC00463



DSC00464



DSC00465