

Photo Album for Hampton, NH Job 29182 January 29, 2016

This week the cab finished in paint. The pump arrived and have valves installed. The body began fabrication. Next week the cab is scheduled to begin on the cab line where cab related content is added while the chassis may begin assembly. The body may begin the paint process.



DSC07080



DSC07081



DSC07082



DSC07083



DSC07084



DSC07085



DSC07086




DSC02428



DSC02429



DSC02430



DSC04043



DSC04044



DSC04045



DSC04046



DSC04047



DSC04048



DSC04049