


# Photo Album for Henniker, NH Job 29296 February 5, 2016

This week the cab began the paint process while the arrived and had valves installed. Next week the cab should finish in paint. The pump house structure and body may begin fabrication.



DSC08005



DSC08006



DSC08007



DSC08008





DSC08009



DSC00116



DSC00117



DSC00118