


Photo Album for Henniker, NH Job 29296 February 19, 2016

This week the cab began on the cab line where cab related content is added. The chassis began assembly. The pump house had trim installed. The body began the paint process. Next week the cab and pump house are scheduled to be merged with the chassis. The body should be nearing completion in paint.




DSC07497



DSC07498



DSC07499



DSC07500



DSC07501



DSC00274



DSC00275



DSC00276



DSC00277



DSC00278



DSC00279



DSC00280



DSC00281



DSC00282



DSC00283



DSC00284



DSC00285



DSC00286



DSC00287



DSC00288




DSC00289



DSC00844



DSC00845



DSC00846



DSC00847



DSC00848



DSC00849



DSC00067



DSC00069



DSC00070



DSC00071



DSC00072