




Photo Album for Henniker, NH Job 29296 March 18, 2016

This week your apparatus completed alignment and initial pump testing and had reflective striping applied. In the next few days your apparatus should complete 3rd party pump testing and be released to final product evaluation which is part of the quality process. This is your last scheduled report.

ITEM NO. 29296

TRUCK NO. 19499098

INTERNAL ORDER NO. 19499826

AERIAL NO.

TORQUE SOX NO. 036444

V.I.N. NO.

CHASSIS BY: ☒ MERCE ☐ CUSTOMER

DEALER: Minuteman Fire & Rescue

CUSTOMER: Hanniker Fire Department

STATE: NH

CITY: Strick

PAINT NO: #899 & #101

SPECIAL INSTRUCTIONS:

HYDR ☐ ELEC ☐ GS ☐ Hoisting ☐ No Trim

☐ Vent Blower ☐ Hose Storing ☐ Special Colors

☐ Backlight ☐ Sign Board ☐ Jamblier ☐ Trachometer

☐ Minuteman Fire Department Truck B

☒ NO GRAPHICS ☐ DOT ONLY

Rev 1.1 08/06/2013



DSC02620

DSC02621



DSC02622



DSC02623



DSC02624



DSC02625



DSC02626



DSC02627



DSC02628



DSC02629



DSC02630



DSC02631



DSC02632



DSC02633



DSC02634



DSC02635



DSC02636



DSC02637



DSC02638



DSC02639



DSC02640



DSC02641



DSC02642



DSC02643



DSC02644



DSC02645



DSC02646



DSC02647



DSC02648



DSC02649



DSC02650



DSC02651



DSC02652



DSC02653



DSC02654



DSC02655



DSC02656



DSC02657



DSC02658



DSC02659



DSC02660



DSC02661



DSC02662



DSC02663



DSC02664



DSC02665



DSC02666



DSC02667



DSC02668



DSC02669



DSC02670



DSC02671



DSC02672



DSC02673



DSC02674



DSC02675



DSC02676



DSC02677



DSC02678



DSC02679



DSC02680



DSC02681



DSC02682



DSC02683



DSC02684



DSC02685



DSC02686