


# Photo Album for Hyannis MA Job 30261 March 3, 2017

This week the cab finished in paint and began on the cab line where cab related content is added. The pump house began initial plumbing. Body panels began fabrication. Next week the cab should continue assembly while the chassis begins assembly. The pump house may begin the paint process. Body panels should be joined in fabrication.



DSC04197



DSC04198



DSC04199



DSC04200





DSC04201



DSC07195



DSC07196



DSC07197






DSC07198



DSC07199



DSC07087



DSC07088



DSC07089



DSC07090



DSC07091