





Photo Album for Keene, NH Job 29809 August 5, 2016

This week the cab finished on the cab line and has been merged with the chassis. The pump house was painted and had trim and harnessing added. The body was nearing completion in paint. Next week, after the pump house is merged, the chassis is scheduled to begin on the main assembly line where the body (after harnessing and trim are added) and water tank should be merged with the chassis.



DSC04433



DSC04434




DSC04435



DSC04436



DSC04437




DSC04438




DSC04439




DSC04440



DSC04441



DSC04442



DSC04443



DSC04444



DSC04445



DSC04446




DSC04447



DSC04448




DSC04449



DSC04450



DSC04451



DSC04452



DSC04453



DSC04454



DSC04455



DSC04456



DSC04457



DSC04458



DSC04459



DSC04460



DSC04461



DSC04462



DSC04463



DSC04464



DSC07146



DSC07147



DSC07148



DSC07149



DSC07150



DSC07151



DSC07152



DSC07153



DSC00287



DSC00288



DSC00289



DSC00290



DSC00291