


Photo Album for Londonderry, NH Job 29507 April 29, 2016

This week the cab began on the line where cab related content is added while the chassis began assembly. The pump house was fabricated while the body began fabrication. Next week the cab is scheduled to be merged with the chassis. The pump house and body should begin the paint process.




DSC04390



DSC04391



DSC04392



DSC04393



DSC04394



DSC00354



DSC00355



DSC00356



DSC00357



DSC00358



DSC00359




DSC00360



DSC00361



DSC00362



DSC07020



DSC07021




DSC07022



DSC07023



DSC07024



DSC07078



DSC07079



DSC07080



DSC07081