





Photo Album for Londonderry, NH Job 29507 May 6, 2016

This week the cab finished on the cab line and has been merged with the chassis along with the pump house. The body began the paint process. Next week the chassis should finish assembly and testing. The body should finish in paint and may be back on the line where harnessing and trim are added.



DSC02371



DSC02372



DSC02373



DSC02374



DSC02375



DSC02376



DSC02377




DSC02378



DSC02379



DSC02380



DSC02381



DSC02382



DSC02383



DSC02384



DSC02385



DSC02386



DSC02387



DSC02388



DSC02389



DSC02390



DSC02391



DSC02392



DSC02393



DSC02394



DSC02395



DSC02396



DSC02397




DSC02398



DSC02399



DSC02400



DSC02401



DSC02402



DSC02403



DSC02404



DSC02405



DSC02406



DSC02407



DSC02408



DSC02409




DSC02410



DSC02411



DSC02412




DSC02413



DSC02414



DSC02415



DSC02416



DSC02417



DSC02418



DSC02419



DSC02420



DSC02421



DSC02422



DSC02423



DSC02424



DSC02425



DSC02426



DSC02427



DSC02428



DSC02429



DSC02430



DSC02955



DSC02956



DSC02957



DSC02958



DSC02959



DSC02960



DSC02961



DSC02962



DSC02963



DSC02964



DSC02965



DSC02966




DSC02967



DSC02968



DSC02969



DSC02970




DSC02971



DSC02972



DSC02973



DSC00190



DSC00191



DSC00192



DSC00193



DSC00194