


Photo Album for Londonderry, NH Job 30294 September 16, 2016

This week the cab began the paint process. The pump house structure began fabrication while valves were installed on the pump. Next week the cab should finish in paint. The pump house structure should have the pump installed. The body may begin fabrication.



DSC02653



DSC02654



DSC02655



DSC02656



DSC02657



DSC02658



DSC02659



DSC02660



DSC07222



DSC07223



DSC07224



DSC07225



DSC07205



DSC07206



DSC07207