


Photo Album for Londonderry, NH Job 30294 September 23, 2016

This week the cab was staged at the end of the paint process. The chassis began assembly. The pump house finished initial plumbing. The body side panels began fabrication. Next week the cab is scheduled to begin on the cab line where cab related content is added while the chassis may begin assembly. The pump house may begin the paint process while body panels are joined in fabrication.



DSC00036




DSC00037



DSC00038




DSC00039



DSC00415



DSC00416



DSC00417



DSC00418



DSC00419



DSC00420



DSC00421



DSC00422



DSC00423



DSC00424




DSC00425



DSC00426



DSC00427



DSC07040



DSC07041



DSC07042



DSC07043



DSC07044



DSC07094



DSC07095



DSC07096