





Photo Album for Londonderry, NH Job 30294 September 30, 2016

This week the cab began on the cab line where cab related content is added while the chassis continued assembly. The pump house began the paint process in metal finishing. The body was staged to begin the paint process. Next week the cab is scheduled to be merged with the chassis and pump house. The body should continue in paint.



DSC04275



DSC04276



DSC04277



DSC04278



DSC04279



DSC04360



DSC04361



DSC04362



DSC04363



DSC04364



DSC04365



DSC04366



DSC04367




DSC04368



DSC04369



DSC04370



DSC04371



DSC04372



DSC04373



DSC04374



DSC04375



DSC04376



DSC04377



DSC04378



DSC04379



DSC04380



DSC07040




DSC07041




DSC07042



DSC07043



DSC07044



DSC00483



DSC00484



DSC00485



DSC00486



DSC00487