





Photo Album for Londonderry, NH Job 30294 October 07, 2016

This week the cab finished on the cab line and has been merged with the chassis along with the pump house. The body continued in paint. Next week the chassis may continue in assembly and testing. The aerial support pedestal may begin assembly. The body should finish in paint and may have harnessing and trim added.



DSC00118



DSC00119



DSC00120



DSC00121



DSC00122



DSC00123



DSC00124



DSC00125




DSC00126



DSC00127



DSC00128



DSC00129



DSC00130



DSC00131



DSC00132



DSC00133



DSC00134



DSC00135



DSC00136



DSC00137



DSC00138



DSC00139



DSC00140




DSC00141



DSC00142



DSC00143



DSC00144



DSC00145



DSC00146



DSC00147




DSC00148



DSC00149



DSC00150



DSC00011



DSC00012



DSC00013



DSC00014



DSC00015