


# Photo Album for Londonderry, NH Job 30294 December 2, 2016

This week the aerial device completed assembly, was pinned to the chassis and calibration and initial aerial testing began on your apparatus. At the time of this report, your apparatus was at the tilt test pad. Next week 3<sup>rd</sup> party aerial testing should be near completion.



DSC08673



DSC08674



DSC08675



DSC08676






DSC08677



DSC08678



DSC08679



DSC08680





DSC08681



DSC08682



DSC08683



DSC08684





DSC08685



DSC08686



DSC08687



DSC08688





DSC08689



DSC08690



DSC08691



DSC08692





DSC08693



DSC08694



DSC08695



DSC08696





DSC08697



DSC08698



DSC08699



DSC08700





DSC08701



DSC08702



DSC08703



DSC08704