Photo Album for Meredith, NH Job 30070 July 29, 2016

This week the cab began the paint process and was nearing completion in paint. The pump house structure was fabricated. A body side panel began fabrication. Next week the cab is scheduled to begin on the cab line where cab related content is added while the chassis may begin assembly. The pump should be installed in the pump house. The body side panels should be joined in fabrication.



DSC00305



DSC00307



DSC00306



DSC00308





DSC00309



DSC07124



DSC07123




DSC07125





DSC07067



DSC07069



DSC07068



DSC07070

