




Photo Album for Meredith, NH Job 30070 August 19, 2016

This week the cab was merged with the chassis along with the pump house. The body finished the paint process along with the body module assembly line, where wire harnessing and trim are added. Next week your apparatus should begin on the main assembly line where the body and water tank are installed.

ITEM NO. 30070

TRUCK NO. 20364864

INTERNAL ORDER NO. 20375409

AERIAL NO.

TORQUE BOX NO. 017051

V.I.N. NO.

CHASSIS BY: ☒ PIERCE ☐ CUSTOMER

DEALER: Minuteman Fire & Rescue Apparatus

CUSTOMER: Town of Meredith

STATE: NH

C/M: Parker

PAINT NO: #50 & #10

SPECIAL INSTRUCTIONS:

☐ Previous Pierce Customer Truck # To Match

☐ DOT ☐ VIP ☐ UL TAGGED

0402 0836 Page 1 of 1 Revised: 02/13/2018

DSC00105



DSC00106



DSC00107



DSC00108



DSC00109



DSC00110



DSC00111



DSC00112



DSC00113



DSC00114



DSC00115



DSC00116



DSC00117



DSC00118



DSC00119



DSC00120




DSC00121



DSC00122



DSC00123



DSC00124



DSC00125



DSC00126



DSC00127



DSC00128



DSC00129



DSC00130



DSC00131



DSC00132



DSC00133



DSC00134



DSC00135



DSC00136



DSC00137



DSC00138



DSC00139



DSC00140



DSC00141



DSC00142



DSC00143



DSC00144



DSC00173



DSC00174



DSC00175



DSC00176



DSC00177