




Photo Album for Nashua, NH Job 30014 September 16, 2016

This week the cab was nearing completion in paint. The pump has valves installed. Next week the cab is scheduled to begin on the cab line where cab related content is added while the chassis may begin assembly. The pump should be installed in the pump house while the body is scheduled to begin fabrication.



DSC02745



DSC02746



DSC02747



DSC02748



DSC02749



DSC02750



DSC07230



DSC07231



DSC07232



DSC07233