




Photo Album for Nashua, NH Job 30014 September 23, 2016

This week the cab finished in paint while the chassis began assembly. The pump house finished initial plumbing. The body finished fabrication. Next week the cab is scheduled to begin on the cab line where cab related content is added while the chassis continues assembly. The pump house and body may begin the paint process.



DSC04024



DSC04025



DSC04026



DSC04027



DSC04028



DSC04029



DSC04030



DSC00402



DSC00403



DSC00404



DSC00405



DSC00406



DSC00407



DSC00408



DSC00409



DSC00410



DSC00411




DSC00412



DSC00413



DSC00414



DSC07030



DSC07031



DSC07032



DSC07033



DSC07034



DSC08036



DSC08037



DSC08038



DSC08039



DSC08040