





Photo Album for Nashua, NH Job 30014 September 30, 2016

This week the cab began on the cab line where cab related content is added while the chassis continued assembly. The pump house was painted and had flexible hose and trim added. The body began the paint process. Next week the cab is scheduled to be merged with the chassis and pump house. The body may have harnessing and trim added.



DSC04254



DSC04255




DSC04256



DSC04257



DSC04258



DSC04143



DSC04144



DSC04145



DSC04146



DSC04147



DSC04148



DSC04149



DSC04150



DSC04151



DSC04152



DSC04153



DSC04154



DSC04155



DSC04156



DSC04157



DSC04158



DSC04159



DSC04160



DSC04161



DSC04162



DSC04163



DSC04164



DSC04165



DSC04166



DSC08037



DSC08038



DSC08039



DSC08040



DSC08041



DSC00478



DSC00479



DSC00480



DSC00481



DSC00482