




Photo Album for Nashua, NH Job 30014 October 07, 2016

This week the cab finished on the cab line and has been merged with the chassis along with the pump house. The body finished in paint and completed the line where harnessing and trim were added. Next week the chassis is scheduled to begin on the main assembly line where the body and water tank should be merged with the chassis.



DSC00232



DSC00233



DSC00234



DSC00235



DSC00236



DSC00237



DSC00238



DSC00239



DSC00240



DSC00241




DSC00242



DSC00243



DSC00244



DSC00245



DSC00246




DSC00247



DSC00248



DSC00249




DSC00250



DSC00251



DSC00252



DSC00253



DSC00254



DSC00255



DSC00256



DSC00257



DSC00258



DSC00259



DSC00260



DSC00261



DSC00262



DSC00263



DSC00264




DSC00265



DSC00266



DSC00267



DSC00268



DSC00269



DSC00270



DSC00271



DSC00466



DSC00467



DSC00468



DSC00469



DSC00470