




Photo Album for New Bedford, MA Job 28768 January 08, 2016

This week the chassis was staged to continue merge testing and assembly. The aerial torque box began assembly. The body modules had harnessing and trim added. Next week the chassis should be merged with the aerial torque box and may begin on the assembly line.

ITEM NO.	28768
TRUCK NO.	18717236
INTERNAL ORDER NO.	18717854
AERIAL NO.	18717859
TORQUE BOX NO.	18717855
V.I.N. NO.	016241
CHASSIS BY:	☒ PIERCE ☐ CUSTOMER
DEALER:	Minuteman Fire & Rescue
CUSTOMER:	New Bedford Fire Department
STATE:	

DSC00118



DSC00119



DSC00120



DSC00121



DSC00122



DSC00123



DSC00124



DSC00125



DSC00126



DSC00127



DSC00128



DSC00129



DSC00130



DSC00131



DSC00132



DSC00133



DSC00134



DSC00135



DSC00136




DSC00137



DSC00138



DSC00139



DSC00140



DSC00141



DSC00142



DSC00143



DSC00144



DSC00145



DSC00146



DSC00147



DSC00148



DSC00149



DSC00150



DSC00151



DSC00152



DSC00153



DSC02098



DSC02099



DSC02100



DSC02101



DSC02102



DSC02103



DSC02104



DSC02105



DSC02106



DSC02895



DSC02896



DSC02897



DSC02898



DSC02899



DSC02900



DSC02901



DSC02902



DSC02903



DSC02904



DSC02905



DSC02910



DSC02911



DSC02912



DSC02913