Photo Album for New Bedford, MA Job 28768 November 20, 2015

Your new Pierce apparatus is now in production. This week the cab began fabrication. In the next report the cab should begin the paint process.

Due to the Pierce Plant Holiday shut down, your next report is scheduled for December 4, 2015.



DSC04000



DSC04002



DSC04001



DSC04003



DSC04004

