




Photo Album for New Bedford, MA Job 28768 December 18, 2015

This week the cab was nearing completion on the cab line where cab related content is installed while the chassis began assembly. The front, mid and rear body modules began the paint process. Next week the cab is scheduled to be merged with the chassis. The aerial torque box may begin assembly. The body modules may finish in paint.

ITEM NO.	28768
TRUCK NO.	18717236
INTERNAL ORDER NO.	18717854
AERIAL NO.	18717859
TORQUE BOX NO.	18717855
V.I.N. NO.	016241
CHASSIS BY:	☒ PIERCE ☐ CUSTOMER
DEALER:	Minuteman Fire & Rescue
CUSTOMER:	New Bedford Fire Department
STATE:	MA
/M:	Streck
PAINT NO:	#90 & #10

DSC02993



DSC02994




DSC02995



DSC02996



DSC02997



DSC02998



DSC02999



DSC03000



DSC03001



DSC03002



DSC03003



DSC03004



DSC03005



DSC03006



DSC03007



DSC03008



DSC03009



DSC03010



DSC03011



DSC03012



DSC03013



DSC03014



DSC03015



DSC03016



DSC03017



DSC03018




DSC03019



DSC03020



DSC03021



DSC03022



DSC03023




DSC03024



DSC03025



DSC03026



DSC03027



DSC03028



DSC03029



DSC03030




DSC03031



DSC07519



DSC07520



DSC07521



DSC07522



DSC07523



DSC07524



DSC07525



DSC07526




DSC07527



DSC07528




DSC07529



DSC07530



DSC07531



DSC07532




DSC07533



DSC07534



DSC07535



DSC00001



DSC00006



DSC00007



DSC00008



DSC00009



DSC00010



DSC00011



DSC00012



DSC00451



DSC00452



DSC00453




DSC00454



DSC00002



DSC00003



DSC00004



DSC00005