





Photo Album for New Bedford, MA Job 28768 December 23, 2015

This week the cab finished on the cab line and has been merged with the chassis. The body modules were nearing completion in paint. In the next report the chassis should continue with merge testing. The aerial torque box may begin assembly. The body modules may have harnessing and trim added.

Due to the Pierce Plant Holiday shut down, your next report is scheduled for Friday, January 8, 2016



DSC07385



DSC07386



DSC07387



DSC07388



DSC07389



DSC07390



DSC07391



DSC07392



DSC07393



DSC07394




DSC07395




DSC07396



DSC07397



DSC07398



DSC07399




DSC07400



DSC07401




DSC07402



DSC07403



DSC07404



DSC07405



DSC07406



DSC07407



DSC08069



DSC08070



DSC08071



DSC08072



DSC08073



DSC08074



DSC08075



DSC08076



DSC08077




DSC08078



DSC08079



DSC08080



DSC08099



DSC08100



DSC08101



DSC08102



DSC08103



DSC08104



DSC08312



DSC08313



DSC08314



DSC08315



DSC08316



DSC08317