

Photo Album for Newbrook, VT

Job # 29192

W/O # 19352537

March 11, 2016

Your new Pierce apparatus is now in production at the Bradenton, FL facility. This week the chassis arrived and is in staging. The lower body modules were fabricated and began the paint process. Next week the chassis should remain in staging. The pump house structure may be fabricated and the lower body should continue in paint.

QUALITY SYSTEM FORM

PW0 #: 19352537 Job #: 29192

Chassis Color: *90 Red Top Color: (Two Tones)

VIN #: 1FVHCYCYXGHHF9473

Customer: Newbrook FD

Contract Manager: Christina Mori

RFP Date: 5/9/16

Rework Number: _____

CONFIGURATION

☐ PUMPER

☒ TANKER

☐ RESPONDER

☐ RESCUE

☐ BRUSH TRUCK

☐ OTHER: _____

Customer Supplied Chassis? Yes ☐ No ☐

DSC06227



DSC06228



DSC06229



DSC06230



DSC06231



DSC06232



DSC06233



DSC06234



DSC06235



DSC06236



DSC06237



DSC06238



DSC06239



DSC06240



DSC06241



DSC06242



DSC06243



DSC06244



DSC06245



DSC06246



DSC06247



DSC06248



DSC06249



DSC06250



DSC06251



DSC06252



DSC06253



DSC06395



DSC06396



DSC06397



DSC06398



DSC06399



DSC06400