


# Photo Album for Newbrook, VT

## Job # 29192

### W/O # 19352537

### March 18, 2016

This week the chassis remained in staging, while the body modules finished the paint process. Next week the chassis should remain in staging, the pump house structure could begin fabrication and the water tank may arrive.



DSC07158



DSC07159



DSC07160




DSC07161





DSC07162



DSC07152



DSC07153



DSC07154



DSC07155



DSC07156



DSC07157